

INSTALLATION INSTRUCTIONS

SAFE BOX HANDLING NOTES - PLEASE READ FIRST


<u>To Open:</u> **1.** Depress bottom latch with a slotted screwdriver and lid will pop out. **2.** Pull top of lid straight out from housing without lifting up. **3.** Once entirely pulled out, lift lid and it will remain in open position until closed.

<u>To Close:</u> **1.** Push lid down without latching bottom. **2.** Push in top hinges until it snaps into place. **3.** Close bottom until it latches. **4.** Optional screw provided to more permanently secure lid to housing.


Mounting Instructions:




Step 1 – Drill 15/16" hole in desired location in duct.



Step 2 – Align opening in mounting flange with hole in duct and attach mounting flange to duct using self-tapping screws. (Insert set screw if desired.)




Step 3 - Insert sensor probe in mounting flange and push until sensor snaps into place (unless using adjustable set screw mounting). Wire through provided bottom or side access points. Additional snap-in conduit adapters available if necessary. Proceed to Configuration Instructions.






Step 1 – Determine wiring location (north side of building if possible). Drill hole, if necessary, then center and attach the mounting flange to building.



Step 2 - If wiring from rear, feed wire from hole into the rear access point on the sensor. Snap sensor onto mounting flange.




Step 3 – If wiring through side access points, pierce grommet with knife or remove and snap in conduit adapter. Additional conduit adapters available if necessary. Proceed to Configuration Instructions.




Step 1 – Feed wires through hole in rear of sensor.



Step 2 - Mount with screws, then make connections.



Step 3 – Snap on cover. Depress hooks through vents with tool to remove.



Configuration Instructions for ALL Tasseron Humidity Sensors:

For optional passive temperature sensor, connect one wire to each quick connect terminal labeled "TEMP" (non-polar).

Instructions for 4 to 20 mA Output

| Terminal | Function |
|----------|---|
| TEMP | 2-pole connection for optional passive temperature sensor (no polarity) |
| VIN | Main power – DC only |
| 4-20mA | Current mode signal output |
| COM | (not used in current mode) |
| VOUT | (not used in current mode) |

DIP Switch Configuration




Figure 1: 4-20mA Output

Step 1 – Be sure the white Output mode DIP switches are in the proper configuration (see Fig 1). For 4-20mA output, DIP switch #2 must be in the LEFT/OFF position. Switch #1 has no function in this mode and is OFF by default.

Step 2 – Terminate control wires in quick connects as indicated in the table above. Only 2 wires are needed for 4-20mA output mode: 1. main power supply and 2. signal output. These wires terminate at "VIN" and "4-20mA".

Step 3 – Power on control/power supply to sensor.

Instructions for 0-5V or 0-10V Output

| Terminal | Function |
|----------|---|
| TEMP | 2-pole connection for optional passive temperature sensor (no polarity) |
| VIN | Main power – AC or DC |
| 4-20mA | (not used in voltage mode) |
| COM | Common |
| VOUT | Voltage signal output |

DIP Switch Configuration






Figure 3: 0-5V Output

Figure 2: 0-10V Output

Step 1 – Be sure the white Output mode DIP switch is in the proper configuration. For 0-5V output, DIP switch #1 must be in the LEFT position and DIP switch #2 must be in the RIGHT position (see Fig 2). For 0-10V output, both #1 and #2 DIP switches must be in the RIGHT positions (see Fig 3).

Step 2 – Terminate control wires in quick connects as indicated in the table above. Three wires are needed for Voltage output mode: 1. main power supply (VIN), 2. common (COM), and 3. signal output (VOUT).

Step 3 – Power on control/power supply to sensor.

